Regency
the first name in solid state

PROFESSIONAL 2 WAY action radio

DATE 1/6/81

SSC Service Bulletin

no. 81-190

TO: ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES & SERVICE CENTERS
ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES REPRESENTATIVES

MODELS AFFECTED: MCU18, MCU34, 34H, MCBU19A, 19B, MCBU35A, 35B

PROBLEM: NO TRANSMITTER OUTPUT POWER FROM CHANNEL 2 WHEN THE AMBIENT TEMPERATURE IS COLD

SOLUTION: CHANGE C302B to .05mf Y5R 50V, P/N 1501-0503-003

TECHNICAL SERVICE DEPARTMENT

REGENCY COMMUNICATIONS, INC.